

# HISTORIC AMERICAN ENGINEERING RECORD

## INDEX TO PHOTOGRAPHS

SILAS C. READ SAWMILL

HAER GA-91

Outlet of Maxwell Lake near North Range Road

Fort Gordon

Richmond County

Georgia

## INDEX TO BLACK AND WHITE PHOTOGRAPHS

Daniel R. Pratt, photographer, March 1995

GA-91-1	View of Read Sawmill masonry dam, pump and earthen dam, facing west
GA-91-2	View of Read Sawmill masonry dam and concrete block retaining wall, facing north
GA-91-3	View of Read Sawmill masonry dam, facing north
GA-91-4	View of Read Sawmill masonry dam, site of submerged sawmill remains and earthen dam, facing north
GA-91-5	View of Read Sawmill masonry dam, facing south
GA-91-6	View of concrete block retaining wall
GA-91-7	View of Read Sawmill masonry dam, West end, showing fractured portion
GA-91-8	View of pump, facing east
GA-91-9	View of sluice gate, north side of masonry dam, facing south
GA-91-10	View of submerged remains of Read Sawmill, showing floor boards, wall boards, tenoned uprights and mortised sill beams.
GA-91-11	View of submerged remains of Read Sawmill, showing earthen dam wooden crib structures

SILAS C. READ SAWMILL  
HAER GA-91  
INDEX TO PHOTOGRAPHS

GA-91-12	View of submerged remains of Read Sawmill, showing floor boards, cross beams and notches for wall post beams.
GA-91-13	View of submerged remains of Read Sawmill, with floor boards removed, showing cross beams, foundation sill and mortises, and horizontal wall boards.
GA-91-14	View of submerged remains of Read Sawmill with most floorboards removed, showing cross beams with mortises, vertical wall boards, and horizontal floor boards.
GA-91-15	View of cross beam with mortise and underlying double floor boards, following removal of structural members from stream
GA-91-16	View of floor boards and wall post beams, following removal of structural members from stream
GA-91-17	View of wall post beam with abutting cross beam, showing chocks
GA-91-18	View of double floor boards with mortises cross beams, showing spikes and flooring nails (Lower board layer exposed)
GA-91-19	View of double floor boards with mortises cross beams, showing spikes and flooring nails (Lower board layer exposed)
GA-91-20	View of half-lapped wall fragment, located in downstream debris field
GA-91-21	View of pegged beams, located in downstream debris field
GA-91-22	View of pegged beams, located in downstream debris field